Wednesday, 12/03/2008 11:12:24 AM User: Linda Lacelle **Process Sheet** : CC-DAR01 Dart Aerospace Ltd. **Drawing Name** : D412-664-209 Customer **Job Number** : 37832 : 10804 **Estimate Number** : D412664209 **Part Number** P.O. Number : RTN FROM HAI : 12/03/2008 S.O. No. : **Drawing Number** This Issue : NC Project Number Prsht Rev. : 11/03/2008 : LANDING GEAR **Drawing Revision** First Issue Type : 00015 Material **Previous Run** Each **Due Date** : 18/03/2008 Qty: 1 Um: Written By Checked & Approved By Comment **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** INSPECT WORK TO CURRENT STEP 1.0 QC5 Comment: INSPECT PART FROM HAI D412-664-209 B36771 PACKAGING 1 PACKAGING RESOURCE #1 2.0 Comment: PACKAGING RESOURCE #1 pick packing kit: 3.0 Bolt AN640A 4.0000 Each(s)/Unit Comment: Qty.: Total: 4.0000 Each(s) Bolt batch 4.0 AN641A Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) C1/50/80 Bolt MS21042L6 Comment: Qty.: 6.0000 Each(s)/Unit Total: 6.0000 Each(s) Nut 08/03/12 M105077 batch

Date:	Wednesday, 12/03/2008 11:12:24 AM	·					
User:	Linda Lacelle	Process Sheet					
Cu	Customer: CC-DAR01 Dart Aerospace Ltd. Drawing Name: D412-664-209						
loh I	Number: 37832	<b>Part Number:</b> D412664209					
Job Number:							
Seq. #:	Machine Or Operation:	Description :					
6	.0 AN960JD616	Washer					
d	Comment: Qty.: 18.0000 Each(s)/Unit	Total: 18.0000 Each(s)					
	Washer batch Mo68	63 AS 08/03/12 (XI)					
7	1.0 QC4	INSPECT 100% KITS FOR COMPLETENESS					
	Comment: INSPECT 100% KITS FOR COM	PLETENESS & DE (R/12(CC)) PACKAGING RESOURCE #1					
8	3.0 PACKAGING 1	PACKAGING RESOURCE #1					
,	Comment: PACKAGING RESOURCE #1						
	REPACKAGE PER PPP						
. ;	USING ORIGINAL B/N 36771	FINAL INSPECTION/W/O RELEASE					
Comment: FINAL INSPECTION/W/O RELEASE							
Job Comple	etion	- 00200 DU					
	·						

Wednesday, 12/03/2008 7:15:00 AM

User:

Linda Lacelle

## **Process Sheet**

Customer

: CC-DAR01 Dart Aerospace Ltd.

**Job Number Estimate Number**  : 37832

: 10804

P.O. Number

This Issue

Prsht Rev.

First Issue

**Previous Run** 

: 12/03/2008

S.O. No. :

Type

: LANDING GEAR

: NC

: 11/03/2008

: 00015

Written By Checked & Approved By

Comment

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

QC5



Comment: INSPECT PART FROM HAI

D412-664-209 B36771

2.0

1.0

PACKAGING 1



Comment: PACKAGING RESOURCE #1

REPACKAGE PER PPP USING ORIGINAL B/N 36771

QC21 3.0

FINAL INSPECTION/W/O RELEASE

PACKAGING RESOURCE #1

Description:

INSPECT WORK TO CURRENT STEP



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



**Drawing Name** 

: D412-664-209

**Part Number** 

: D412664209 : RTN FROM HAI **Drawing Number** 

**Project Number** 

**Drawing Revision** Material

**Due Date** : 18/03/2008 Qty:

1 Um:

Each

Da/e: U/ser:	Tuesday, 1/15/2008 7:47:41 AM Kim Johnston	Process Sheet		
Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: 412 X-TUBE ,LOW NARROW	N AFT
Job Number	: 36771	Diawing Haine	. HIZ ATIODE LEGININA	W OL I
Estimate Num				
P.O. Number	;	Part Number	: D412664209	
This Issue	: 1/15/2008	Drawing Number Project Number	: D412-664-209 <del>U/R</del> A : N/A	
Prsht Rev. First Issue	: NG : // Type : LANDING GEA		: WA	
Previous Run	***	Material	:	
Written By	:	Due Date	: 2/4/2008 Qty:	1 Um: Each
Checked & Ap	proved By :			
Comment	: Est Rev:A New Issue 07.09.12 Est Rev:B ECN 1100 08-01-11	EC verified by: JLM DD verified by EC		
Additional Pro	duct			
Job Number:				
Seq. #:	Machine Or Operation:	Description :		
Seq. #:	DC	DOCUMENT CONTROL		
1.0		DOOOINIETAL OOMATAGE		
Co	omment: DOCUMENT CONTROL		1,18k(18,18) (18,138)	1 1
	Photocopy bluefile and create labels as	per PPP D212-664-209 CHG001	(	08.01.20
2.0	D6008132P	Crosstube extrusion		
	! (###)##			
	18818118118181118			
Со	mment: Qty.: 1.0000 Each(s)/Unit Total:	1.0000 Each(s)		_
	Pick:			
	Qty Part number Description Batch			
	1 D6008-132 Crosstube	<del></del>		
3.0	Check OD = 3.250"; ID = 2.375"	MORI SEIKI CNC LATHE LARGE		
3.0	MORI SEIK! 	MUKI SEINI UNU LATTIL LANGL		
Co	mment: 1-TURN AS PER FOLIO FA708 & DWG	- D412-664-249		
	FOLIO REV:	DTIZ OUT ZIO,	REI	FERENCE ONLY
	DWG REV:		~•	EKENCE ON
				- ONLY
	2-DEBURR AS REQUIRED			
4.0	QC2	INSPECT PARTS AS THEY COME (	OFF MACHINE	
Co	mment: INSPECT PARTS AS THEY COME OF	E MACHINE	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
5.0	QC8	SECOND CHECK		
		SECOND OF LEST.		
Col	mment: SECOND CHECK		1 (80 (18 (8) (10 0) 8 (1) (10 0)	
	0200110 0112011			